


Instructions for Use: Wellness Screens


Brand Name of Product	Wellness Screens
Generic Name of Product	Wellness Screens
Product Code Number(s)	WS-001, WS-002
Intended Use	Provide a see-through barrier with a pass-through opening.
Range of Applications for Product	Workstations, desks, receptions windows, etc.
Key Specifications of Product	<ul style="list-style-type: none"> • Crystal clear cast acrylic • Heavy duty • Free standing, portable • Chemical resistant <div> WS-001 (Pick-Up Style): <ul style="list-style-type: none"> • 32" H x 24" W • Slits: 7 5/16" L • Opening of slits: 1/4" W • Clear acrylic: 1/4" thick • 7" W on each side of opening • Arch: 10" W </div> <div> Acrylic Holder: <ul style="list-style-type: none"> - 14 9/16" H x 12 1/4" W - Slits: 7 5/16" L - Opening of slits: 1/4" W - Clear acrylic: 1/4" thick - Legs: 4 3/6" W - Arch: 4" W </div> <div> WS-002 (Pick- Up Style): <ul style="list-style-type: none"> • 32" H x 32" W • Slits: 7 3/8" L • Opening of slits: 1/4" W • Clear acrylic: 1/4" thick • 10" W on each side of opening • Opening: 12" W x 7" H </div> <div> Acrylic Holder: <ul style="list-style-type: none"> - 12 9/16"H x 12 1/4" W - Slits: 5 3/8" L - Opening of slits: 1/4" W - Clear acrylic: 1/4" thick - Legs: 4 3/16" W - Arch: 4" W </div>

Shipping Conditions & Requirements	
Storage Conditions	
Packaging Contents	
Shelf Life	

Instructions for Using Product	
Description of Use(s)	Provide a see-through barrier with a pass-through opening.
Preparation for Use	
Diagrams (drawings, pictures)	WS-001



WS-002



Steps for Use of Product

1. Hold the clear acrylic screen with both hands.
2. Align the slits at the bottom of the screen with the slits on the clear acrylic holder.
3. Slide the screen down into slits of the acrylic holder.

Interpretation of Test Results

Contraindications of Test Results

Documentation

Special Warnings and Cautions

Disposal

Reprocessing Instructions

Point of Use	
Preparation for Decontamination	
Disassembly Instructions	
Cleaning – Manual	Clean with warm soapy water. Gentle soap and rinse with clean water.
Cleaning – Automated	
Disinfection	Approved disinfectants: <ul style="list-style-type: none"> • Bleach: 1/3 cup per gallon of water to dilute • Isopropyl alcohol: wipes or sprays containing at least 70% • Hydrogen peroxide: 3-5% (do not dilute) • Spray cleaner <ol style="list-style-type: none"> 1. Spray cleaner on a soft cloth or microfiber cloth. 2. DO NOT apply cleaner directly to the screen. 3. Apply mild pressure to wipe.
Drying	
Maintenance, Inspection, and Testing	
Reassembly Instructions	
Packaging	
Sterilization	
Storage	
Additional Information	
Related Healthmark Products	
Other Product Support Documents	PPE Brochure, PPE Price List
Reference Documents	
Customer Service Contact	Healthmark Industries Company, Inc. 18600 Malyn Blvd. Fraser, MI 48026 1-586-774-7600 healthmark@hmark.com hmark.com

2020-08-20 Suzanne Latta